

BUENOS AIRES City, October 10<sup>th</sup>, 2019.

Mr. Ville Salonen  
Technical Representative  
GA Telesis Engine Services Oy  
Helsinki Airport  
Turbiniikuja 6  
01530, Vantaa  
Finland

**Subj.:** Repair Station Certification in accordance  
with RAAC 145.-

Mr. Ville Salonen

We are glad to contact you in order to inform that according to the results of the inspection performed on **GA Telesis Engine Services Oy (ANAC Code# 1B-645)** facilities; this Office has decided to issue ANAC Certificates. Attached to this letter you will find the Operations Specifications Certificate and the Repair Station Certificate.

On the other hand, this Office ratifies discrepancies detailed on document "ACTA DE INSPECCIÓN - Anexo 2" dated on September 20<sup>th</sup>, 2019 and requires you that within the next 30 days starting upon receiving this letter to send a Corrective Action Plan (CAP). This CAP must include at least the following topics:

- 1) Root Causes (identify because the deviation in regards with the procedure occurred).
- 2) Immediate action (explain what was done immediately after and until definitive corrective action is be taken).
- 3) Corrective Action (must correct the root cause).
- 4) Implementation dates (date of completion of the final corrective action).
- 5) Responsible Persons (responsible for the final corrective action).
- 6) Evidences (can be copies of forms, documents, photographs, etc.).

It is worth mentioning that regarding the discrepancy found on Approved Contractors audits, we request that, prior to sending a component or accessory from an Argentine engine to one of this companies, it must be ensured that the audit and subsequent quality control have been executed correctly in accordance with the applicable procedures.

Attached to this letter you will find the acceptance of the ANAC-DA Supplement Rev. 0 and the Contract Maintenance Function List Rev. 16/09/19.

If you have any question, please do not hesitate in contacting us.

Respectfully Yours,



Guillermo Martín Molina  
Dirección de Aeronavegabilidad  
Dirección Nacional de Seguridad Operacional